

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

T-U-1

CORNERS OF THE PUBLIC SURVEY

T. 147N R. R2W 5th Mer.

Corner common to Sections

25, and 30
Corner consists of a Iron (rod) in place



State condition 2E

Dimensions above ground 1" 28 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Galena Willow

Diameter 2 2

Bearing N 92 22 W N 13 5 E

Distance 351 366

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

(Signature)

(Date)

(Title)

38

CORNERS OF THE PUBLIC ENTRY

Give any further facts which will aid in finding this corner again.


chains distant.

from which this corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near corner)

T. 142N R. 27W S. 34E Mer