

U. S. Department of Agriculture
FOREST SERVICE

Posted

Q-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 28W 5th P. Mer.

8 1/16 Corner common to Sections

19, and 24 (R29W)

Corner consists of a G. L. O. pipe (not) in place

State condition good

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

S. C. Ruder

(Signature)

Tech. Foreman

(Title)

10/9/34

(Date)

Section 19 T147 R28
19 chains North SW corner

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147N R. 28W 5th P. Mer.

U. S. Department of Agriculture
FOREST SERVICE

Q-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 28 W 5th Mer.

5 1/6

Corner common to Sections

19, and 24 (Range 29 W)

Corner consists of a G.L.O. PIPE (~~mark~~) in place

State condition good

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

S. Rudser

(Signature)

Tech. Foreman

(Title)

10/9/34

(Date)

746

19 chains North SW cor. sec 19 T197 R2B

Corner again.

Give any further facts which will aid in finding this


----- chains distant.

----- from which this Corner bears

side of -----

tree ----- inches diameter, on the

----- Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 197 N. R. 28 W. 5th Mer.

U. S. Department of Agriculture
FOREST SERVICE

Q-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 28 5 Mer.

5/16 Corner common to Sections
19, and 24

Corner consists of a staple (not) in place
State condition good

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

(Signature)

(Date)

(Title)

746

U.S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

CORNER OF THE PUBLIC SURVEY

Corner again.

Give any further facts which will aid in finding this

chain distant,

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

<p>See</p>	<p>See</p>	<p>See</p>	<p>See</p>
<p>See 19</p>	<p>See 19</p>	<p>See 11</p>	<p>See 11</p>

(Make sketch of topography near Corner)