

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

J3
Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 28 W 5 P Mer.



1/4 Sec. Corner common to Sections
7, and 18

Corner consists of a square cedar post in place
State condition good

Dimensions above ground 4" X 4" X 24" inches.
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species	<u>Spruce</u>	<u>Spruce</u>		
Diameter	<u>8"</u>	<u>5"</u>		
Bearing	<u>S-12-W</u>	<u>N-47-W</u>		
Distance	<u>54.2</u>	<u>46.6</u>		

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Wm H Pletcher

Signature.


Forest Ranger

Title.

11/26/28
Date.

T. 147N R. 28W S. P. Mer.

8-3027 (Make sketch of topography near corner.)



Metal Location Poster is on a spruce

tree 6 inches diameter, on the N.W.

side of corner

from which this corner bears S-52-E

26 ^{links} _{equals distant}

Give any further facts which will aid in finding this

Corner again.

App. 3 cts. S. of cleared E. Whine.

N 5 line thru corner cleared.

Corner 3 cts. inside of South

swamp boundary, in path of spruce

at antonack poles.