

U. S. DEPARTMENT OF AGRICULTURE

FOREST SERVICE

L5
Posted

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 28 W 56 Mer.

1/4 Corner common to Sections

17, and 18

Corner consists of a Sq. Stake (one) in place


State condition Good 3/4" iron pipe

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? Re-survey corner

C. B. Smith

Signature.

FR


12-21-28

Date.

Title.

(Make sketch of topography near corner.)

T. 147N R. 28W 5p Mer.



Metal Location Poster is on a

tree _____ inches diameter on the

side of _____

from which this Corner bears _____

chains distant _____

Give any further facts which will aid in finding this

Corner again.

MC 1126 N on 7°

ack. ~~marked~~ position

16 ch E mark

green bushes on N on 7°

~~all other~~

23 ch S to metal ~~marker~~

at 33 ch.