

U. S. DEPARTMENT OF AGRICULTURE  
FOREST SERVICE

Posted AS

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 + 148 N. R. 22 W Mer. 5

See Corner common to Sections

5, 6, 31, and 32

Corner consists of a sq stake in place


State condition As properly described

Dimensions above ground \_\_\_\_\_ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 32

S 3?

BT

grown out

BT (new)

-(old)

-

new BT

Species WP Elm WP Corn

Diameter N 59° E 12" 20 10"

Bearing 17 1/2 N 30° E S 35 W S

Distance 75' 20' 30' 50'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Signature.

FR


Date.

10-13-22

Title.

T. 142N R. 22W S Mer. 8-3027

(Make sketch of topography near Corner.)



Metal Location Poster is on a \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.  
 Give any further facts which will aid in finding this Corner again.

Corner area with a back  
 information from 2 sections to  
 change the south west to a  
 bearing of N 10° E  
 bearing on post N on 10° E