

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

Posted
J 17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 28 W 5th Mer.

Section _____ Corner common to Sections

15, 14, 10, and 11

Corner consists of a Squared Aspen (not) in place



State condition Stub rotten

Dimensions above ground 60 inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____
Diameter _____
Bearing _____
Distance _____

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____


Roy A. Chapman
Signature.

Ranger
Title.

1/4/28
Date.

T. 157 N. R. 28 W. 5th Mer.

8-2027 (Make sketch of topography near corner.)



Metal Location Poster is on a ~~Aspen~~ tree 12" inches diameter, on the ~~West~~ side of corner

from which this corner bears ~~Dire East~~ 20 lks. chains distant.

Give any further facts which will aid in finding this

Corner again.

~~Line Monkey faced Corner on west edge of alder patch -~~