

U. S. DEPARTMENT OF AGRICULTURE
FOREST SERVICE

*File
R-107*

Chap

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *147 N* R. *28 W* Mer. *5*

148 N

Sec

Corner common to Sections

2

3

34

and

35

Corner consists of a

square bush stake

State condition

New

Dimensions above ground

40

inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>None found</i>	<i>None found</i>	<i>None found</i>	<i>None found</i>

Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

No its recent

C. Blatter

Signature.


Date.

10-8-28

R.R.

Title

(Make sketch of topography near corner.)



Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant,

Give any further facts which will aid in finding this

Corner again.

Monter facing
 - small beam mark
 12" beam E
 9" beam N
 11" beam W

12' beam square as in

17th N to Dixon Lake road (road)
 1/4 Sec 2 E 1/4 Sec 2 E 1/4 Sec 2 E