

U. S. Department of Agriculture
FOREST SERVICE

J-23

Posted

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 28 W. Mer...... 1/4 Corner common to Sections....., 12, and 13Corner consists of a 2 sided stone. (with) in placeState condition GoodDimensions above ground 3.5" dia., 2 1/2" high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Species dead B.S.P.F.Diameter 4 1/2"Bearing N. 42° EDistance 6 ft.Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

W. Banks

(Signature)


9/18/34

(Date)

T.F.

(Title)

(Make sketch of topography near Corner)



Metal Location Poster is on a *Black Spruce*

tree *6* inches diameter, on the

side of

from which this Corner bears *N 19° E*

8 ft. chains distant.

Give any further facts which will aid in finding this

Corner again.

Corner is located in a stand of 7c. Corner stake is a black spruce stump leaning east of 45° angle.