

U. S. Department of Agriculture
FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 29 W. 5th. P. Mer.
Quarter Corner common to Sections

31, and 32

Corner consists of an Ash Post (iron) in place
State condition Good

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B.T.		Mod. New B.T.	
1/2 S 51			
B.T.			

Species Spruce Aspen Dead Aspen
 Diameter 18" 8" 4"
 Bearing N. 50° W. S. 42° E. S. 28° W.
 Distance 17 54 45

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

John A. Gjalhaug

(Signature)


12/11/30

(Date)

Jr. Civil Eng.

(Title)

Corner again.
 Give any further facts which will aid in finding this
 chains distant.
 from which this Corner bears **N. 45° W.**
 side of **Iron**
 tree **2** inches diameter, on the **N.W.**
 Metal Location Poster is on **an ASPEN**



(Make sketch of topography near Corner)