

Form 874-9—Revised May, 1915
U. S. Department of Agriculture
FOREST SERVICE

L-9

Chippewa NATIONAL FOREST



CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 29 W 5th P. Mer.

Quarter Corner common to Sections
16, and 17

Corner consists of a Tam'c. Post (Set) in place
State condition Good


Dimensions above ground 36 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tam'c. Tam'c.

Diameter 4" 4"

Bearing N34°W N59°E

Distance 49 40

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Established from M.C. only 6000
chains north

John A. Gjølhaug

(Signature)

Jr. Civil Engineer

2/1/40


(Date)

(Title)

L-9

COMPASS OF THE FIELD PARTY
GIVE ANY FURTHER FACTS WHICH WILL AID IN FINDING THE
CORNER AGAIN.

0.25 chains distant
from which this Corner bears
S. 46° E.
side of Tree
3 inches diameter, on the S. E.
Metal Location Poster is on a Tarn's



(Make sketch of topography near Corner)