

**U. S. Department of Agriculture**  
**FOREST SERVICE**

Chippewa NATIONAL FOREST

**CORNERS OF THE PUBLIC SURVEY**

T. 147 N R. 29 W 5th P. Mer.

Section

Corner common to Sections

8, 9, 16, and 17

Corner consists of a Cedar Post ~~corner~~ in place

State condition Good

Dimensions above ground 36 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig.	B.T.		
B.T.			

Species Tam. Down

Diameter 7"

Bearing S4°E

Distance 226

Do you believe this to be a genuine Land Office Corner? yes

If not, why? \_\_\_\_\_

John A. Gjelhaug

(Signature)

Jr. Civil Engineer

2/1/40

(Date)

(Title)

Section 17  
Section 16  
Section 9  
Section 8

Corner again.

Give any further facts which will aid in finding this

2.43 chains distant.

from which this Corner bears


N2°W

side of Tree

tree 4 inches diameter, on the North

Metal Location Poster is on a

WILLOW



(Make sketch of topography near Corner)