

U. S. Department of Agriculture

FOREST SERVICE

117

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 29 W. 5th. P. Mer. Quarter Corner common to Sections

26, and 27

Corner consists of a Maple Post ~~xxxx~~ in place


State condition Good

Dimensions above ground 40 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Mkd. Now B.T.

$\frac{1}{2}$
S 27

$\frac{1}{2}$
S 20



B.T.

B.T.

Rotten

Species Aspen Sp. N. Oak Aspen

Diameter 12" 7" 8"

Bearing S. 85° E. N. 85° W. N. 75° E.

Distance 50 85 87

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Set corner on old orig. line.

John A. Gjelberg

(Signature)

12/8/20

(Date)

Jr. Civil Eng.

(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of tree

tree 10 inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. M. R. R. 28 N. 2. Mer.