

U. S. Department of Agriculture

FOREST SERVICE

T-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147^{**} R. 29W 5th Mer.

Quarter Corner common to Sections

25, and 26

Corner consists of a Iron pipe with (not) in place


State condition brass cap

Dimensions above ground 2"-12" inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



BT

BT



Species Maple Aspen

Diameter 18 14

Bearing S25E S49W

Distance 31 37

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Walter Haberele

(Signature)

8/20/40

Proj. Asst.

(Date)

(Title)

T-21 98

CORNER OF THE PLUMB SURVEY

Corner station

Give any further facts which will aid in finding this

chain distant

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a **The Marking Trees**

