

Form 874-B—Revised May, 1918  
U. S. Department of Agriculture  
FOREST SERVICE

E-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 29W 5th Mer.

Section Corner common to Sections  
1, 2, 11, and 12

Corner consists of a Cor. in road (not) in place



State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147N  
R29W  
S1

T147N  
R29W  
S11

BT

BT

Species Aspen J. Pine

Diameter 10" 12"

Bearing N46E S42W

Distance 1.60 1.45

Do you believe this to be a genuine Land Office Corner? No

If not, why?

Walter Haberle

(Signature)

9/19/39

(Date)

Leader

(Title)

E-21

Corner again.

Give any further facts which will aid in finding this


chain distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. L. 47N

R. 29W

5th

E-21 Mer.