

Form 874-9—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

V-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 29<sup>W</sup> 5th Mer.  
 Quarter Corner common to Sections

25, and 36  
 Corner consists of a Iron pipe with (not) in place  
 State condition brass cap

Dimensions above ground 2'-10" inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.  
 CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

$\frac{1}{2}$ S 8/25	$\frac{1}{2}$ S/36		
BT	BT		

Species Birch Birch  
 Diameter 6 6  
 Bearing S56E N65W  
 Distance .09 .39

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_

Walter Haberle

(Signature)

8/19/40

(Date)

Proj. Assist.

(Title)

V-23

Geological Survey

Washington, D.C.

# CORNERS OF THE PUBLIC SURVEY

Section 25, Township 36 N., Range 29 W., Mer. 5th

Corner again

Give any further facts which will aid in finding this


chain distant

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a The berrying trees



(Make sketch of topography near Corner)