

U. S. Department of Agriculture
FOREST SERVICE

Posted

.....Chippewa..... NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T146 & 147N R.28 & 29W 5th P. Mer.

Section

Corner common to Sections

31, 36, 6, and 1

Corner consists of a GLO. pipe & brass cap in place


State condition good---est. 1932

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T146N
R28W
S6.BT

T146N
R29W
S1.BT

T147N
R29W
S36.BT

T147N
R28W
S31.BT

SE

SW

NW

NE

Species Aspen Ash Aspen Aspen

Diameter 10.2" 6.1" 10.1" 8.6"

Bearing S10°E S43°W N25°W N64°E

Distance 13.7' 33.6' 19.4' 21'

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

W. Banks

(Signature)

Tech. Foreman

(Title)

10/10/34

(Date)

Find in opening. Hooks piled
around pipe. Aspen pole type.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree. inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)

T146 & 147N R. 28 & 29W 5th P.