

U. S. Department of Agriculture
FOREST SERVICE

V25

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147N R. 2829W 5th Mer.

Section Corner common to Sections
25, 30, 31, and 36

Corner consists of Iron pipe (not) in place
State condition with brass cap

Dimensions above ground inches
Sketch grooves, letters, figures, or notches, on proper face or edge.
CARDINAL POSITION DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147N R29W S.36	T147N R29W s25	T147N R29W s31	T147N R29W 30
BT	BT	BT	BT

Species Aspen	Aspen	Spruce	Spruce
Diameter 10"	8"	8"	6"
Bearing S33W	N48W	N25E	S13E
Distance .20	.19	.03	.30

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Walter Haberle
(Signature)

17/8/39/
(Date)


Leader
(Title)

V-25

U. S. DEPARTMENT OF THE INTERIOR
BUREAU OF LAND MANAGEMENT

CORNER OF THE NE 1/4

Corner again...
 Give any further facts which will aid in finding this
 chiding distant.
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on a



(Also sketch of topography near Corner)

V-25

T. 142N R. 28 29W 51N 52E