

Form 874-B—Revised May, 1918  
 U. S. Department of Agriculture  
 FOREST SERVICE

V-16-17

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 29 W. 5th. P. Mer.



Meander Corner common to Sections  
 \_\_\_\_\_, \_\_\_\_\_, 27, and 34

Corner consists of a Wood Post ~~xxxx~~ in place  
 State condition Good

Dimensions above ground 40 inches  
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B.T.			
B.T.			

Species Tam'e

Diameter 3"

Bearing S. 66° 30' W.

Distance 23

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? \_\_\_\_\_


H. Hoard (Signature)

8/21/39 (Date)

Compass Man. (Title)

V-16-17

Metal Location Poster is on a **T.M.'s.**  
 tree **5** inches diameter, on the **S.E.**  
 side of **Tree**  
 from which this Corner bears **S. 55° E.**  
**0.41** chains distant.  
 Give any further facts which will aid in finding this  
 Corner again.



(Make sketch of topography near Corner)