

U. S. Department of Agriculture
FOREST SERVICE

X-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 30 W 5th P. Mer.

Section Corner common to Sections
31, and 36 T147N R31W

Corner consists of a Cement Mon. ~~stone~~ in place

State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T147N
R31W
S 36

T146N
R31W
S 1

T146N
R30W
S 6

T147N
R30W
S 31

B.T.

B.T.

B.T.

B.T.

Species Elm Elm Aspen Aspen

Diameter 14" 14" 12" 10"

Bearing N61°W S65°W S74°E N45°E

Distance 2.67 4.67 61 85

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

Hugh M. Hoard

(Signature)

Compass Man

(Title)

2/20/40

(Date)

Corner again.

Give any further facts which will aid in finding this


0.45 chains distant.

from which this Corner bears N48°W

side of Tree

tree 3 inches diameter, on the N. W.

Metal Location Poster is on a 1/2 as per



(Make sketch of topography near Corner)

T. 147 N. R. 30 W. 5th P. Mer.