

U. S. Department of Agriculture
FOREST SERVICE

T-2

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 30 S. 42 Mer.

C.W. or 1/4 9 1/2 Corner common to Sections
.....,, and 30

Corner consists of a Wooden Stake (not) in place
State condition Good

Dimensions above ground 48 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of is located

..... Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>No B.T.</i>			

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner?

If not, why?


Murphy
(Signature)

10/6/36
(Date)

(Title)

UNITED STATES DEPARTMENT OF THE INTERIOR
 BUREAU OF LAND MANAGEMENT
 CORNER LOCATION POSTER

Corner again.
 Give any further facts which will aid in finding this
 chains distant
 from which this Corner bears
 side of
 tree inches diameter, on the
 Metal Location Poster is on * *with 1/2" post*



(Make sketch of topography near Corner)