

U. S. Department of Agriculture  
FOREST SERVICE

9.3

Chiffewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 30 5th Mer.

e 1/4 Corner common to Sections  
....., ....., and 19

Corner consists of a ✓ (not) in place  
State condition ✓

Dimensions above ground ✓ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

B 1/4
S-19

B 1/4
S-19

--

--

BT
----

BT
----

--

--

Species Basswood Elm

Diameter 14" 8"

Bearing S 65 W N

Distance 15 ch 24 ch

Do you believe this to be a genuine Land Office Corner? ya

If not, why? .....

[Signature]  
(Signature)

6/27/35  
(Date)

(Title)

*[Faint, mostly illegible text on ruled lines]*

Corner again.

Give any further facts which will aid in finding this

chains distant.

*15*

from which this Corner bears

*S 65 W*


side of

*road*

tree *14* inches diameter, on the

*North*

Metal Location Poster is on a *Banner*



(Make sketch of topography near Corner)