

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 30 W 5th P. Mer. Quarter

Corner common to Sections 4, and 9

Corner consists of a Cedar post (not) in place
State condition Good

Dimensions above ground 40 inches inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B.T.

1/4s 4			10
-----------	--	--	----

B.T.	B.T.		
------	------	--	--

Species N. Pine J. Pine

Diameter 1 1/4" 8"

Bearing N 2° W S 10° W

Distance 23 39 1/2

Do you believe this to be a genuine Land Office Corner? **Yes**

If not, why? _____

JOHN A. GJELHAUG

(Signature)


Jr. Civil Engineer

(Title)

10-22-38

(Date)

Metal Location Poster is on a N. Pine tree 14 inches diameter, on the South side of Tree from which this Corner bears $32^{\circ} E$ 0.23 chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 141 N. R. 30 W. S. 14 P. Mer.