

U. S. Department of Agriculture  
FOREST SERVICE

R-13

..... NATIONAL FOREST  
**CORNERS OF THE PUBLIC SURVEY**

T. 447 R. 30 Mer.

..... Corner common to Sections  
21, 22, 23, and 24

Corner consists of a Wooden (~~not~~) in place  
State condition rather

Dimensions above ground 12" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of ..... is located .....

Pits are located .....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species .....

Diameter .....

Bearing .....

Distance .....

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? .....

.....

.....

4/25/35  
(Date)

(Signature)  
[Signature]  
(Title)

*Handwritten notes on lined paper, including a large number '10' and some illegible text.*

Corner again.

Give any further facts which will aid in finding this

..... *10* chains distant.

from which this Corner bears

*S*

side of .....

tree *3* inches diameter, on the

Metal Location Poster is on a *Aspen*

		Sec. <i>37</i>	Sec. <i>37</i>
Sec. <i>27</i>	Sec. <i>27</i>	Sec. <i>27</i>	Sec. <i>27</i>

(Make sketch of topography near Corner)