

U. S. Department of Agriculture  
FOREST SERVICE

J-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 30 5th Mer.

Quarter Corner common to Sections  
12, and 13

Corner consists of a wooden stake (not) in place  
State condition fair braced

Dimensions above ground \_\_\_\_\_ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

1/4			
-----	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.


Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner?

If not, why? \_\_\_\_\_

M. J. Murphy  
(Signature)

10-16-34  
(Date)

(Title)

Dist. in line with 10' E of small  
bridge and directly south of  
the bridge's peak on N side of  
meadow.

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)