

UNITED STATES GEOLOGICAL SURVEY
 DEPARTMENT OF THE INTERIOR
 BUREAU OF LAND MANAGEMENT
 FIELD OFFICE

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears


side of

tree

tree *4* inches diameter, on the

oppon
W out

Metal Location Poster is on a



(Make sketch of topography near Corner)

T. 147 R. 30 S. 14 Mer.

Form 874-S—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

2-24

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *147* R. *30* *5th* Mer.

1/16 # *15* Corner common to Sections
36, _____, _____, and _____


Corner consists of a _____ (not) in place
State condition _____

Dimensions above ground _____ inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species _____

Diameter _____

Bearing _____

Distance _____

Do you believe this to be a genuine Land Office Corner? _____

If not, why? _____

Duff M Johnson
(Signature)

fall-1957
(Date)

(Title)