


Metal Location Poster is on a Basswood tree 8 inches diameter, on the East side of Tree from which this Corner bears  $0^{\circ}40'$  chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 N. R. 31-30 W. Mer. 6-1

U. S. Department of Agriculture

FOREST SERVICE

G-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 31 W. 5th P. Mer.

Quarter Corner common to Sections

12, and 7

Corner consists of a (not) in place

State condition

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

Orig. B.T. J 1/4 6.12

--

--

J
---

B.T.

--

--

--

Species Basswood

Diameter 8"

Bearing N. 81° W.

Distance 40

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? Is

K. Styler

(Signature)

Compass Man

(Title)

1/17/38

(Date)

G-1