


SECTION 31-37
 T. 147 N. R. 31 E.
 5th Mer.

Metal Location Poster is on a tree inches diameter, on the side of from which this Corner bears chains distant. Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 147 N. R. 31 E. 5th Mer. C-1

Form 374-B Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

C-1

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 31-32 5th Mer.

E. 1/4 cor. of S. 1 Corner common to Sections

1, and 6

Corner consists of a pipe and stake (not) in place


State condition Fair

Dimensions above ground 10 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E




NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



No Bearing Trees

Species

Diameter

Bearing

Distance

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

Murphy

(Signature)

Enrollee

4/16/36

(Date)

(Title)

C-1