


Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the side of \_\_\_\_\_ from which this Corner bears chains distant \_\_\_\_\_ Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

U. S. Department of Agriculture

FOREST SERVICE

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 31 5th Mer.

1/16 corner #9 Corner common to Sections/  
6, , and

Corner consists of a Wooden stake (not) in place



State condition Fair

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 S.	1/16 S.		
BT	BT		

Species Tom. Cedar

Diameter 4" 8"

Bearing S. 45° W. N. 45° W.

Distance .05 ch. .18 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

*Murphy*  
Murphy

4/15/36

(Date)

Enrollee

(Title)