

U. S. Department of Agriculture

FOREST SERVICE

E3

E-3

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N R. 31 W 5th P. Mer.

Quarter Corner common to Sections 6, and 7

Corner consists of a Cedar post (set) in place

State condition Good

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

County B. T.'s

1/4 S
6

1/4 S
6

--

--

B.T.

B.T.

--

--

Species Cedar Cedar

Diameter 10" 6"

Bearing N. 32° W N. 72° E

Distance 10 8

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

K.V. Styer

(Signature)

Leader

(Title)

8-16-38

(Date)

E-3