


Metal Location Poster is on a *Clear* tree 7" inches diameter, on the *East* side of *Stream* from which this Corner bears *33* chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 117 R. 31
 Mer. 526
 O-19

U. S. Department of Agriculture

FOREST SERVICE

P
B
36
0-19

019

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 R. 31 5th Mer.

NC 074 5 1/6 Corner common to Sections

and 23

Corner consists of a 4 1/2 (not) in place


State condition Good

Dimensions above ground 10 inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

CV 9
S-23

CV 9
S-23

BT

BT

Species Cedar Cedar

Diameter 8" 7"

Bearing S20W N20E

Distance 39.2 33.2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

(Signature)

8/30/36 (Date)

(Title)

0-19