

Corner again.

Give any further facts which will aid in finding this


0.27 1/2 chains distant.

from which this Corner bears N. 76° W

side of Post

area 6 inches diameter, on the West

Metal Location Poster is on a Cedar fence post



(Make sketch of topography near Corner)

p. 21

T. 147 N. R. 31 W. 5th P. Mer.

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

821
 P-21

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 147 N. R. 31 W. 5th P. Mer.

Quarter Corner common to Sections
23, and 24

Corner consists of a Brass cap on 1" pipe (not) in place

State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/4 S 23			
B.T.			

Species Cedar

Diameter 5"

Bearing S. 75° 30' W

Distance 59 1/2

Do you believe this to be a genuine Land Office Corner? Yes

If not, why? _____

John A. Gjelhaug
 (Signature)

Jr. Civil Engineer
 (Title)

7-11-38
 (Date)

P-21