

CONTRACT NO. 1000 PUBLIC SURVEY
SECTION 19, 20, 29, 30

Corner again.

Give any further facts which will aid in finding this


0.067 chains distant.

from which this Corner bears N80°E

side of Tree

tree 4 inches diameter, on the East

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

P.O. 5

Form 874-S—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

P-Q-5
~~125~~

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY.

T. 147 N R. 31 W 5th P. Mer.

Meander Corner common to Sections
19, and 20

Corner consists of a Brass Cap Iron ^{Pipe} (not) in place

State condition Good

Dimensions above ground 6 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

MC
S20

MC
S19

B.T.

B.T.

Species N. Pine Cedar

Diameter 10" 8"

Bearing N48°E N74°W

Distance 21 33

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Hugh M. Hoard

(Signature)

Compass Man

(Title)

2/15/40

(Date)

P-Q-5