

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

XI

----- NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. ¹⁴⁸⁻²⁵ ~~148-26~~ R. Line w 5th Mer.

1/4 Corner common to Sections
 -----, -----, 31, and 36-----

Corner consists of a cedar post (not) in place
 State condition fair

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

	<u>1/4</u>		<u>1/4</u>
	<u>Sec</u>		<u>Sec</u>
	<u>36</u>		<u>31</u>

N W S E

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		<u>1/4</u>	
		<u>Sec</u>	
		<u>31</u>	
		<u>BT</u>	

Species ----- R. Spr. -----

Diameter ----- 7" -----

Bearing ----- S 75° E -----

Distance ----- 57 LKS. -----

Do you believe this to be a genuine Land Office Corner? no

If not, why? No notes covering this corner in my field notes.

Virgil D. Smith

(Signature)

6-6-56

(Date)

G. D. A.

(Title)

Corner again.

Give any further facts which will aid in finding this


~~201ky~~ ~~chance~~ distant.

from which this Corner bears *N 85 W*

side of *Tree*

tree *8* inches diameter, on the *WEST*

Metal Location Poster is on a *Town*



(Make sketch of topography near Corner)

T 148-26 R. Lane W 5th Mer.