

61  
posted

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 44 N. R. 20 E. S. 5 Mer.

Corner common to Sections

7, and 12

Corner consists of a Iron pipe in place



State condition Good

Dimensions above ground 2" inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species \_\_\_\_\_

Diameter \_\_\_\_\_

Bearing \_\_\_\_\_

Distance \_\_\_\_\_

Do you believe this to be a genuine Land Office Corner? No

If not, why? Re-surveyed

J. W. ...  
(Signature)

Estimator  
(Title)

11-27-33  
(Date)

Old log building 5 m. N. of  
about 2 chains & 800 yds  
fence & at the end of  
aligned right hand

Corner again.

Give any further facts which will aid in finding this


chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a



(Make sketch of topography near Corner)