

U. S. Department of Agriculture
FOREST SERVICE

M-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *148 N* R. *25 W* *5th* Mer.

5 1/16 Corner common to Sections
-----, and *17*

Corner consists of a *1/2" Iron Pipe* (not) in place

State condition *Good*

Dimensions above ground *6* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

1/16 #6

1/16 #6
517

BT

Species *NP* *NP*

Diameter *5"* *4"*

Bearing *N2-30W* *N70W*

Distance *90L* *1.9L*

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? -----

Donald Poole

(Signature)

12-12-34

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)