

U. S. Department of Agriculture
FOREST SERVICE

N-9

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W 5 Mer.

Sec. Corner common to Sections

16, 17, 20, and 21

Corner consists of a 4" Cedar (not) in place

State condition good 2" iron pipe

Dimensions above ground 36" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

| | | | |
|----|----|----|----|
| S | S | S | S |
| 17 | 20 | 21 | 16 |

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|---------|---------|--|
| | S 20 | S 21 | |
| | BT | BT | |

Species Cedar Cedar

Diameter 8" 9"

Bearing S38N S19E

Distance 48 li 36 li

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Ervin Meagher

(Signature)

9-24-35


(Date)

Field Ass't

(Title)

Corner again.
Sec 15 15 71 N of
Lake in spruce swamp

Give any further facts which will aid in finding this
4871 ~~chairs~~ distant.
from which this Corner bears N38E
side of Tree
tree 8 inches diameter, on the N.E.
Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

T. 198N R. 25W 5 Mer.

U. S. Department of Agriculture
FOREST SERVICE

1-9

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W _____ 5 Mer.

Sec. _____ Corner common to Sections
16, 17, 20, and 21

Corner consists of a 4" cedar (~~not~~) in place

State condition good { 2" iron pipe }

Dimensions above ground _____ 36" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

| | | | |
|--|--|--|--|
| | | | |
|--|--|--|--|

N W S E

| | | | |
|----|----|----|----|
| S | S | S | S |
| 17 | 20 | 21 | 16 |

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

| | | | |
|--|---------|---------|--|
| | S 20 | S 21 | |
| | B.T | B.T | |

Species _____ Cedar cedar

Diameter _____ 8" 9"

Bearing _____ S38W S19E

Distance _____ 48 Li 36 Li

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

Ervin Meagher

(Signature)

9-24-35

(Date)

Field Ass't

(Title)

Sec. 15 156 L. N
of Lake in Spruce
Swamp

Corner again.

Give any further facts which will aid in finding this


78 L. ~~thru~~ distant.

from which this Corner bears N38E

side of Tree

tree 8 inches diameter, on the W E

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

T. 148 N. R. 25 W. 5 Mer.