

U. S. Department of Agriculture

FOREST SERVICE

E-11

Chippewa NATIONAL FOREST
 CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W 5th Mer.

1/4 Corner common to Sections
 _____, _____, 4, and 9

Corner consists of a 4" cedar ~~rod~~ in place
 State condition good (1" iron pipe)

Dimensions above ground 2'6" - 3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		S	
4		9	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

_____ Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S			
4			
B.T.			

Species W. PINE

Diameter 28"

Bearing N 5 E

Distance 23 li

Do you believe this to be a genuine Land Office Corner? YES

If not, why? _____

E. Meeker

(Signature)

Field Ass't


(Title)

9-9-35

(Date)

Corner again.
COR. IS ON FENCE LINE
LARD ROLLING
SECOND GROWTH
ASPEN

Give any further facts which will aid in finding this
237.1 ch~~at~~ distant.
from which this Corner bears
55W
side of tree
tree 28 inches diameter, on the
Metal Location Poster is on a
WIPINE STUMP



(Make sketch of topography near Corner)

T. 148 N. R. 25 W. 576 Mer.

U. S. Department of Agriculture

FOREST SERVICE

E-11

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W 5th Mer.

1/4 Corner common to Sections
4, and 9

Corner consists of a 4" cedar (not) in place

State condition good (1" iron pipe)

Dimensions above ground 2'6" - 3" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		S	
4		9	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S			
4			
B.T.			

Species W. pine

Diameter 28"

Bearing N 5 E

Distance 23 Li

Do you believe this to be a genuine Land Office Corner? *yes*

If not, why? _____

E. M. ...
(Signature)

9-9-35
(Date)

Field Ass't
(Title)

CORNER IS ON FENCE LINE
LAND ROLLING SECOND
GROWTH ASPEN

Corner again.

Give any further facts which will aid in finding this


23 L. ^{or less} distant.

From which this Corner bears

SSW

side of tree

Metal Location Poster is on a W. PINE STUMP
tree 28 inches diameter, on the S



(Make sketch of topography near Corner)

T. 148 N. R. 25 W. 5th Mer.

U. S. Department of Agriculture

FOREST SERVICE

E-11

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W 5th Mer.

E 1/6 Corner common to Sections

, 4, and 9

Corner consists of a 2" iron pipe (set) in place


State condition good

Dimensions above ground 8" high inches


Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S
AS
9

B.T.

B.T.

Species Spruce Spruce

Diameter 5" 6"

Bearing N 8 E S 3 W

Distance 29 Li 37 Li

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

E. Meagher

(Signature)

9-6-35

(Date)

Field Ass't

(Title)

CORNER IS ON S. SIDE
OF SPRUCE SWAMP
AT A FENCE COR.

Corner again.


Give any further facts which will aid in finding this

22 ft. ~~chain~~ distant.

from which this Corner bears 815 W

side of tree

Metal Location Poster is on a spruce tree 5 inches diameter, on the S.W.



(Make sketch of topography near Corner)

T. 148 N. R. 25 W. 5th Mer.