

U. S. Department of Agriculture
FOREST SERVICE

E-12

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 140 N R. 25 W 5th Mer.

E 1/4 Corner common to Sections
4, and 9

Corner consists of a 1" iron pipe (set) in place



State condition good

Dimensions above ground 8" high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Spruce

Spruce

Diameter 5"

6"

Bearing N8E

S3W

Distance 29 Li

37 Li

Do you believe this to be a genuine Land Office Corner? yes

If not, why? _____

E. Mungler

(Signature)

9-6-35

(Date)

Field Ass't

(Title)

CORNER 150N. S. SIDE
OF SPRUCE SWAMP
AT A FENCE CORNER

Corner again.


Give any further facts which will aid in finding this

22.1! - chains distant.

From which this Corner bears S 15 W

side of tree

Metal Location Poster is on a spruce
tree 5 inches diameter, on the S.W.



(Make sketch of topography near Corner)

T. 148 N. R. 25 W. 5th Mer.