

U. S. Department of Agriculture
FOREST SERVICE

~~11-5~~
M-5

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 14 N R. 25 W 5th Mer.

5 1/6 Corner common to Sections
17, and 18

Corner consists of a no post (not) in place
State condition

Dimensions above ground _____ inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

--	--	--	--

<u>BT</u>	<u>BT</u>		
-----------	-----------	--	--

Species JP JP

Diameter 5" 5"

Bearing N5E S10W

Distance 0.30 0.15

Do you believe this to be a genuine Land Office Corner? No

If not, why? Co Engineer

1923
OK as described above
1 BT is 2 ft so. of woods rd.
I put up yell. tag. S.P.R. 8-17-29
(Signature)

(Date)

(Title)

Corner again.

Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of

tree inches diameter, on the

Metal Location Poster is on a

	Sec.		Sec.
	Sec.		Sec.

(Make sketch of topography near Corner)

T. R. Mer.