

U. S. Department of Agriculture  
FOREST SERVICE

A19

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W 5 Mer.

----- 14 Corner common to Sections  
-----, -----, 2, and 35

Corner consists of a 3" cedar (not) in place  
State condition poor

Dimensions above ground 3' inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of ----- is located -----

----- Pits are located -----

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S 35			
B.T			

Species W. Birch

Diameter 12"

Bearing N 43 W

Distance 47 li

Do you believe this to be a genuine Land Office Corner? yes

If not, why? -----

-----

-----

Erwin Meagher  
(Signature)

8-1-35  
(Date)

Field Ass't  
(Title)

Hand Hill and head  
under flash around  
cor. Hider Swamp  
1.50 chains S. of cor.

Corner again.

Give any further facts which will aid in finding this


tree. Chains distant.

from which this corner bears S 60 W

side of tree

tree 10 inches diameter, on the S.W

Metal Location Poster is on a Maple



(Make sketch of topography near corner)

T. 148 N R. 25 W 5 Mer.

U. S. Department of Agriculture  
FOREST SERVICE

A-19

Chippewa NATIONAL FOREST  
CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W ..... 5 Mer.

..... 1/4 Corner common to Sections  
....., ....., 2, and 35

Corner consists of a 3" Cedar ..... (~~not~~) in place



State condition poor

Dimensions above ground 3' ..... inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



Mound of ..... is located.....

Pits are located.....

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>S</u> <u>35</u>			
<u>BT</u>			

Species W. Birch.....

Diameter 12".....

Bearing N 43 W.....

Distance 47 li.....

Do you believe this to be a genuine Land Office Corner? yes

If not, why? .....


Ernie Mergler  
(Signature)

8-1-35  
(Date)

Field Ass't  
(Title)

LAND HILL AND HEART  
UNDER PUSH AROUND  
COR RIDER SWAMP  
ABOUT 1.50 chains  
S of cor.

Corner again.  
Give any further facts which will aid in finding this  
64 ft. ~~obscure~~ distant.  
From which this Corner bears S 60 W  
side of tree  
tree 10 inches diameter, on the S.W  
Metal Location Poster is on a Maple



(Make sketch of topography near Corner)

T. 148 N R. 25 W 5th Mer.

U. S. Department of Agriculture  
FOREST SERVICE

A-19

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W 5 Mer.

1/4 Corner common to Sections  
2, and 35

Corner consists of a 3" cedar (not) in place

State condition poor

Dimensions above ground 3' high inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S		S	
35		2	
N	W	S	E

NW	SW	SE	NE

Mound of \_\_\_\_\_ is located \_\_\_\_\_

Pits are located \_\_\_\_\_

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

S			
35			
B.T.			

Species W. Birch

Diameter 1 1/2

Bearing N43W

Distance 47 Li

Do you believe this to be a genuine Land Office Corner? yes.

If not, why? \_\_\_\_\_

Erwin Meagher

(Signature)

Field Ass't

(Title)

8-1-35

(Date)

Land hill and heavy  
under brush around  
cor. older swamp  
about 1.50 chains  
S of cor

Corner again.

Give any further facts which will aid in finding this


64 ft. ~~thous~~ distant.

from which this Corner bears S 60 W

side of tree

tree 10 inches diameter, on the S. W

Metal Location Poster is on a Maple



(Make sketch of topography near Corner)

T. 148 N R. 25 W 5 74 Mer.