

Signatures Copy

U. S. Department of Agriculture
FOREST SERVICE

P
822

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. *148* R. *25* Mer. *5th*

1/4 # *A* Corner common to Sections
, and *24*


Corner consists of a *iron pipe + 4" Post* (not) in place
State condition

Dimensions above ground *30* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Betula* *Betula*

Diameter *9"* *5"*

Bearing *N68°W* *S21°W*

Distance *55.165* *105.8160*

Do you believe this to be a genuine Land Office Corner?

If not, why? *County corner markers*
scattered on O.T.'s

1/12/37
(Date)

J. M. ...
(Signature)

Asst. Clerk
(Title)

FCR


FOREST SERVICE

Chippewa National Forest

CASS LAKE, MINN.

JUL 19 1937

RECEIVED



(Make sketch of topography near Corner)

Corner again.

Give any further facts which will aid in finding this

chains distant.

80

from which this Corner bears S 21° W

side of

tree

tree 4 inches diameter, on the

SM

Metal Location Poster is on a ASPEN

Mer.

54

T. 148 N R. 25 W

U. S. Department of Agriculture
FOREST SERVICE

P-22

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W Mer. 39



1/16 * 4 Corner common to Sections
, and 24

Corner consists of a iron pipe 4" dia (not) in place
State condition

Dimensions above ground 3 inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Balsam Balsam

Diameter 1" 5"

Bearing N 68° W S 11° W

Distance 55 lks. 125 lks.

Do you believe this to be a genuine Land Office Corner?


If not, why? County records of corner
erected on B.T.

M. M. Muebeck
(Signature)

7/12/37
(Date)

S. Clerk
(Title)

(Make sketch of topography near Corner)



Metal Location Poster is on a

Aspen

tree 4 inches diameter, on the

side of

from which this Corner bears

S 21° W

chains distant.

80

Give any further facts which will aid in finding this

Corner again.

T. 148 N. R. 25 W. S 4 Mer.

U. S. Department of Agriculture
FOREST SERVICE

P-22

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W 35 Mer.

1/16 1/4 Corner common to Sections
23, 24, and 25


Corner consists of a 4" B.T. (not) in place
State condition

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Balsam Balsam

Diameter 4" 5"

Bearing N 68° W S 21° W

Distance 55 102

Do you believe this to be a genuine Land Office Corner? _____

If not, why? County corner markers
marked on B.T.'s.

Y. Kinaback
(Signature)

St. Clerk
(Title)

(Date)

Corner again.

Give any further facts which will aid in finding this


Sp. chains distant.

from which this Corner bears S 71° W

side of tree

tree 4 inches diameter, on the S W

Metal Location Poster is on a *A span*



(Make sketch of topography near Corner)

Mer.

T. 14th R. 25 W