

U. S. Department of Agriculture

FOREST SERVICE

P 23

Shippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 25 W. 3rd Mer.

Center 1/4 Corner common to Sections
, and 24


Corner consists of a Iron pipe - 1" Post (not) in place
State condition

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



B.T

B.T



Species Bellwood Ash

Diameter 7" 10"

Bearing S 80° E N 41° E

Distance 37.8 links 31.2 links

Do you believe this to be a genuine Land Office Corner? No

If not, why? Set by County Surveyor

Data obtained from county Notes

Murbeck
(Signature)

7/21/37
(Date)

Sr. Clerk
(Title)

Corner again.


Give any further facts which will aid in finding this

chains distant.

from which this Corner bears

side of tree
Metal Location Poster is on a
Ranches diameter, on the

FOREST SERVICE
RECEIVED
JUL 9 1937
LAKE, MINN



(Make sketch of topography near Corner)

T. 148 N. R. 25 W. 59 Mer.

U. S. Department of Agriculture

FOREST SERVICE

P-23

Shigemo NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. *48 N* R. *25 W* *34* Mer.

Center 1/4 Corner common to Sections
....., and *24*

Corner consists of a *single 4" post* (not) in place
State condition

Dimensions above ground *30* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

N	W	S	E

NW	SW	SE	NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<i>3</i>	<i>3</i>		
<i>14</i>	<i>14</i>		
<i>BT</i>	<i>BT</i>		

Species *B. Wood* *Asht*

Diameter *7"* *10"*

Bearing *S 82° E* *N 41° E*

Distance *27.8 lks* *34.0 lks*

Do you believe this to be a genuine Land Office Corner? *no*

If not, why? *set by county surveyor*


St. Clerk
(Signature)

St. Clerk
(Title)

7/12/31
(Date)

(Make sketch of topography near Corner)

T. 41 N. R. 25 W. S. 2 Mer.



Metal Location Poster is on a *B. I. Casswood*

tree *7* inches diameter, on the *NW*

side of *Tree*

from which this Corner bears *N 80° W*

chains distant.

Give any further facts which will aid in finding this

Corner again.

U. S. Department of Agriculture

FOREST SERVICE

P-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W 5th Mer.

Center 1/4 Corner common to Sections

and 24

Corner consists of a iron pipe - 4" fast (not) in place


State condition

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E



NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species B. Wood Ash

Diameter 7" 10"

Bearing S 80° E N 71° E

Distance 39.8 links 31.0 links

Do you believe this to be a genuine Land Office Corner? No

If not, why? Jersey County Survey

Data taken from County Notes


J. P. Beck (Signature)

7/12/32 (Date)

S. Clerk (Title)

(Make sketch of topography near Corner)

T. 48 N. R. 25 W. Mer.



Metal Location Poster is on a

tree inches diameter, on the

side of

from which this Corner bears

chains distant.

Give any further facts which will aid in finding this

Corner again.