

*Superior*  
*copy*

U. S. Department of Agriculture  
FOREST SERVICE

8

N 23

*Shingora* NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. *48 N* R. *25 W* S. *3* Mer.

*14* Corner common to Sections  
*13*, and *24*



Corner consists of a *iron pipe 4" dia* (not) in place  
State condition

Dimensions above ground *34* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Box Elder* *Poplar*

Diameter *14* *17*

Bearing *N 59° W* *N 66° E*

Distance *29.1 links* *50.7 links*

Do you believe this to be a genuine Land Office Corner?   
If not, why?

Data read from County Surveyor


*J. J. ...*  
(Signature)

*7/12/37*  
(Date)

*...*  
(Title)

Give any further facts which will aid in finding this  
 Corner again.  
 from which this Corner bears  
 chains distant.  
 inches diameter, on the  
 side of  
 tree  
 Metal location Poster is on a

U.S. DEPARTMENT OF AGRICULTURE  
 FOREST SERVICE  
 RECEIVED  
 JUL 19 1937  
 CARROLL COUNTY, MISSISSIPPI



(Make sketch of topography near Corner)

T. 148 N. R. 25 W. S. 4 Mer.

U. S. Department of Agriculture

FOREST SERVICE

N-23

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 25 W Mer. 35

1/4 Corner common to Sections 13, and 24


Corner consists of a iron pipe 4" dia (not) in place State condition

Dimensions above ground 30 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION


DIAGONAL POSITION



Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species gov't Pine, Poplar

Diameter 14 12"

Bearing N 59° W N 66° E

Distance 39.1 links 50.7 links


Do you believe this to be a genuine Land Office Corner? If not, why?

(Signature)

7/12/27 (Date)

(Title)

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the \_\_\_\_\_ side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.  
 Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 148 W. R. 15 N. 5<sup>th</sup> Mer.

U. S. Department of Agriculture

FOREST SERVICE



*copy*

*Chippewa* NATIONAL FOREST *N-23*

CORNERS OF THE PUBLIC SURVEY

T. *148 N* R. *25 W* S. *54* Mer.

*1/4* Corner common to Sections

*13*, and *24*



Corner consists of a *iron pipe 4" dia.* (not) in place  
State condition

Dimensions above ground *30* inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION




N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Asp. Pine* *Poplar*

Diameter *14"* *12"*

Bearing *N. 59° W.* *N. 66° E.*

Distance *37.14* *50.74*

Do you believe this to be a genuine Land Office Corner? .....

If not, why? .....

*Data recd. from county surveyor*


*J. J. Beck*  
(Signature)

*7/2/37*  
(Date)

*Clerk*  
(Title)

Metal Location Poster is on a tree \_\_\_\_\_ inches diameter, on the side of \_\_\_\_\_ from which this Corner bears \_\_\_\_\_ chains distant.

Give any further facts which will aid in finding this Corner again.



(Make sketch of topography near Corner)

T. 148 N. R. 25 W. 54 Mer.