

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

523
posted

NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 109 R. 25 S. Mer.

Measured on Corner common to Sections
Mud Lake, 12, and 13

Corner consists of a none (not) in place
 State condition ✓

Dimensions above ground _____ inches.

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

--	--	--	--

N W S E NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

		<i>Blas</i>	<i>Blas</i>
		<i>Blas</i>	<i>Blas</i>

Species _____ *Sp.* *Sp.*
 Diameter _____ *6* *4 1/2*
 Bearing _____
 Distance _____


Do you believe this to be a genuine Land Office Corner? ✓

If not, why? _____

 (Signature)
1921 33 *Estimador*
 (Date) (Title)

Metal Location Poster is on a _____ inches diameter, on the
 side of _____ from which this Corner bears
 _____ chains distant.
 Give any further facts which will aid in finding this
 Corner again.

*Corner at base of tree
 from corner west to top of*



(Make sketch of topography near Corner)

T. 145 R. 25 Mer.