

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

X-21

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148N R. 26W 5th Mer.

quarter Corner common to Sections
35, and 36

Corner consists of a wood post (not) in place
State condition good

Dimensions above ground 4"-4"-30" inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

<u>1/4</u>			<u>1/4</u>
<u>S35</u>			<u>S36</u>
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

T. 148N
R. 26W
S. 35

S/35

B.T.

B.T.

Species Cedar Birch stub

Diameter 8 14

Bearing N44E N50W

Distance 60 49

Do you believe this to be a genuine Land Office Corner? NO

If not, why? COUNTY CORNER

Walter H. Fisher
(Signature)

3/26/41
(Date)

Asst. Sup.
(Title)

Corner again.

Give any further facts which will aid in finding this


24 LKS. chains distant.

from which this Corner bears

side of

tree 3 inches diameter, on the SW

Metal Location Poster is on a Cedar



(Make sketch of topography near Corner)

Mer. X-21

T. L. HEN R. 26 W 57