

C1
P

U. S. Department of Agriculture
FOREST SERVICE

Chinswa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148th R. 27th 5th Mer.

1/4 Corner common to Sections
1, and 6

Corner consists of a Corner placed (not) in place



State condition by Crew

Dimensions above ground inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION



N W S E

NW SW SE NE

Mound of is located

Pits are located

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species Tamarack

Diameter 8"

Bearing N85°E

Distance 1.05 ch.

Do you believe this to be a genuine Land Office Corner? Yes

If not, why?

W. E. ...
(Signature)

6/25/35
(Date)

Party Chief, CCC
(Title)

WATER RESOURCES DIVISION

CORNER OF THE PUBLIC SUPPLY

Corner again.

Gives any further facts which will aid in finding this

chain distant.

from which this Corner bears


S I A

side of SGC. 6

tree 5 inches diameter, on the

Metal Location Poster is on a

SPT.



(Make sketch of topography near Corner)