

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

G3

P

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 27 E. 5th Mer.
 Center $\frac{1}{2}$ Corner common to Sections
 3, and

Corner consists of a Spruce post (not) in place
 State condition very rotten, broken down.

Dimensions above ground _____ inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

Illegible			
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

C. $\frac{1}{2}$	C. $\frac{1}{4}$	C. $\frac{1}{2}$	C. $\frac{1}{2}$
S. 3	S. 3	S. 3	S. 3
B. T.	B. T.	B. T.	B. T.

Species Tam. Spruce Tam. Spruce
 Diameter snag 8" 12" stump
 Bearing N. 23° W. S. 26° E. S. 35° W. N. 43° W.
 Distance 0.15 0.17 0.16 0.14

Do you believe this to be a genuine Land Office Corner? Yes
 If not, why? _____

Arthur H. Jager
 (Signature)

8/12/35.
 (Date)

Chief of party, C.C.C.
 (Title)

[Faint, illegible handwriting on ruled lines]

Corner again.

Give any further facts which will aid in finding this

chains distant.

0.17

from which this Corner bears


N. 26° W.

side of tree

tree 8 inches diameter, on the Northwest

Metal Location Poster is on a

Spring



(Make sketch of topography near Corner)

T. 148 N. R. 27 W. S. 4th Mer.