

Form 874-9—Revised May, 1918
U. S. Department of Agriculture
FOREST SERVICE

25

Chippewa NATIONAL FOREST
CORNERS OF THE PUBLIC SURVEY

T. 148 N R. 26 W 5 Mer.

1/4 Corner common to Sections
31, and 32

Corner consists of a Wooden stake (not) in place
State condition Rotted at ground

Dimensions above ground 60 inches

Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

--	--	--	--

N W S E

--	--	--	--

NW SW SE NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>Forest Service Marker</u>			

Species Norway Pine

Diameter 20"

Bearing S 97° E

Distance 38 lks.

Do you believe this to be a genuine Land Office Corner? No.

If not, why? No scribbling on tree. Only old Blaze

W. A. Brills

(Signature)


1/24/34
(Date)

C. O. P.

(Title)

(Make sketch of topography near Corner)

T. 145 N. R. 27 W. S. Mer.



Metal Location Poster is on a *Norway Pine* tree *8.0* inches diameter, on the *SE* side of *said tree* from which this Corner bears *38 1/2°* chains distant.

Give any further facts which will aid in finding this Corner again.