

Form 874-9—Revised May, 1918
 U. S. Department of Agriculture
 FOREST SERVICE

27

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 148 N. R. 27 W. 5th Mer.

$\frac{1}{4}$ Corner common to Sections
 _____, _____, 20, and 29

Corner consists of a Cedar post (not) in place
 State condition Good

Dimensions above ground 30 inches
 Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION

DIAGONAL POSITION

S.	$\frac{1}{4}$	S.	$\frac{1}{4}$
20		29	
N	W	S	E

NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

148 N.			
R. 27 W.			
S. 29 $\frac{1}{4}$			
B. T.			

Species Cedar
 Diameter stump
 Bearing S. 38° E.
 Distance 0.86

Do you believe this to be a genuine Land Office Corner? Yes
 If not, why?

Arthur H. Jager

(Signature)

8/14/35
 (Date)

Chief of party, C. C. C.
 (Title)

Handwritten notes on a series of horizontal dashed lines.

Corner again.

Give any further facts which will aid in finding this


0.41 chains distant.

from which this Corner bears N. 41° E.

side of

tree inches diameter, on the Northeast

Metal Location Poster is on a



(Make sketch of topography near Corner)

U. S. Department of Agriculture
FOREST SERVICE

R-7

Chippewa NATIONAL FOREST

CORNERS OF THE PUBLIC SURVEY

T. 128N R. 27W 5th Mer.

1/4 Corner common to Sections
28 + 29, and _____

Corner consists of a ced. post (not) in place
State condition Good

Dimensions above ground 30" inches
Sketch grooves, letters, figures, or notches, on proper face or edge.

CARDINAL POSITION				DIAGONAL POSITION			
S 30	1/4 4	S 29	1/4 4				
N	W	S	E	NW	SW	SE	NE

Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.

<u>1st</u> <u>2nd</u> <u>3rd</u>			
<u>BT</u>			

Species cedar
Diameter 5.5
Bearing S 28° E
Distance 1.86

Do you believe this to be a genuine Land Office Corner? Yes
If not, why? _____

Arthur H. [Signature]
(Signature)
8/14/35
(Date)
Land Party
(Title)

Corner again.

Give any further facts which will aid in finding this


chains distant. 0.111

from which this Corner bears N10°E

side of

tree inches diameter, on the Pole

Metal Location Poster is on a pole 1/2 mile



(Make sketch of topography near Corner)

Mer.

T. 148N R. 97W 52