

U. S. Department of Agriculture
FOREST SERVICE

Posted

Chippewa NATIONAL FOREST


CORNERS OF THE PUBLIC SURVEY

T. *178 N* R. *27 W* Mer. *5*

C 1/4 Corner common to Sections *7*, and

Corner consists of a *plate* (not) in place
State condition *Good*


Dimensions above ground *26* inches
Sketch grooves, letters, figures, or notches, on proper face or edge.



Mound of _____ is located _____

Pits are located _____

Sketch markings of Bearing Trees (or Rocks) in proper box and fill blanks below, giving bearings from Corner to Trees and Distances in Links.



Species *Red Cedar*

Diameter *14* *9*

Bearing *58° 30' E*

Distance *30 ft* *39 ft*

Do you believe this to be a genuine Land Office Corner? *Yes*

If not, why? _____

Joe Karl
(Signature)
Estimator
(Title)

7-19-37
(Date)

Metal Poster of
Metal Building
Cottrell Camp

Corner again.

Give any further facts which will aid in finding this

15 ft. chains distant.

from which this Corner bears

S. 25° E

side of


Tree

tree 4 inches diameter, on the

N 87° E

Metal Location Poster is on a

Post



(Make sketch of topography near Corner)